

Cityside Garage Ltd.
 330 Hopping Brook Rd.
 Unit 3
 Holliston, MA 01746

508-429-4336

Fax # 508-429-2178



service@citysidegarage.com

Invoice

Invoice #	Bill To	
87148	COPLEY MOTORCARS CORPORATION 37 CHESTNUT STREET NEEDHAM, MA. 02492	
8/30/2022	Customer Phone	781-444-4646

Vin #	SALDH1287PA920210	Plate #	NE31ET	MODEL	D110	YEAR	1993	Odom. in	24,983	Odom. out	24,994
-------	-------------------	---------	--------	-------	------	------	------	----------	--------	-----------	--------

Item	Description	Qty	Rate	Amount
LABOR - CO...	1. OIL SERVICE AND COPLEY CHECKOVER	1	150.00	150.00
PARTS	GENUINE OIL FILTER	1	19.95	19.95
PARTS	15W40 OIL	7	8.99	62.93
ENVIROMEN...	OIL DISPOSAL FEE	1	10.00	10.00
LABOR - CO...	2. TRUCK RUNS POORLY, PLEASE ADVISE	2	150.00	300.00
	- FOUND THE INTAKE TUBE TO HAVE A COUPLE TEARS IN IT, WHICH COULD RESULT IN RUNNING BADLY.			
	- FOUND THE SPARK PLUGS TO BE OLDER AND RUSTY.			
	- SUGGEST PERFORMING A FULL TUNE UP WITH AIR FILTER AND REPLACING THE INTAKE TUBE AND GOING FROM THERE.			
	- REMOVED AND REPLACED INTAKE TUBE			
	- PERFORMED TUNE UP.			
PARTS	INTAKE TUBE	1	139.99	139.99
PARTS	HOSE CLAMPS	2	4.50	9.00
PARTS	SPARK PLUGS	8	3.95	31.60
PARTS	IGNITION WIRES	1	99.95	99.95
PARTS	CAP	1	64.80	64.80
PARTS	ROTOR	1	32.95	32.95

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW ANY WARRANTIES ON THE PRODUCT SOLD HERIEEN ARE THOSE MADE B THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NETHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN CASE OF FIRE, THEFT OR OTHER CAUSES BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Subtotal
Sales Tax (6.25%)
Total
Payments/Credits
Balance Due

x _____

Cityside Garage Ltd.
 330 Hopping Brook Rd.
 Unit 3
 Holliston, MA 01746

508-429-4336

Fax # 508-429-2178



service@citysidegarage.com

Invoice

Invoice #	Bill To	
87148	COPLEY MOTORCARS CORPORATION 37 CHESTNUT STREET NEEDHAM, MA. 02492	
8/30/2022	Customer Phone	781-444-4646

Vin #	SALDH1287PA920210	Plate #	NE31ET	MODEL	D110	YEAR	1993	Odom. in	24,983	Odom. out	24,994
-------	-------------------	---------	--------	-------	------	------	------	----------	--------	-----------	--------

Item	Description	Qty	Rate	Amount
PARTS	AIR FILTER	1	16.95	16.95
LABOR - CO...	3. THE CHECK ENGINE LIGHT IS ON, PLEASE ADVISE - CONFIRMED. PULLED CODES: MISFIRE DETECTED - SEE LINE #2	0	150.00	0.00
LABOR - CO...	4. CUSTOMER STATES THE TRUCK WANDERS WHILE DRIVING. THERE IS A LOT OF PLAY IN THE BOX, RECOMMEND REPLACING THE STEERING BOX. - REMOVED AND REPLACED STEERING BOX AND REFILLED SYSTEM. CENTER STEERING WHEEL	2.8	150.00	420.00
PARTS	STEERING BOX	1	1,695.99	1,695.99
Shipping & H...	HEAVY WEIGHT SHIPPING	1	36.95	36.95
PARTS	ATF	2	7.99	15.98
LABOR - CO...	5. CUSTOMER STATES PLEASE MAKE THE FRONT AND REAR PLATES SO THEY ARE EASY TO TAKE ON AND OFF. - REMOVED BOTH PLATES AND REPLACED ANY DAMAGED INSERTS.	0.5	150.00	75.00
PARTS	HARDWARE DURING CHECKOVER FOUND	1	20.00	20.00

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW ANY WARRANTIES ON THE PRODUCT SOLD HEREIN ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN CASE OF FIRE, THEFT OR OTHER CAUSES BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

x _____

Subtotal
Sales Tax (6.25%)
Total
Payments/Credits
Balance Due

Cityside Garage Ltd.
 330 Hopping Brook Rd.
 Unit 3
 Holliston, MA 01746

508-429-4336

Fax # 508-429-2178



service@citysidegarage.com

Invoice

Invoice #	Bill To	
87148	COPLEY MOTORCARS CORPORATION 37 CHESTNUT STREET NEEDHAM, MA. 02492	
8/30/2022	Customer Phone	781-444-4646

Vin #	SALDH1287PA920210	Plate #	NE31ET	MODEL	D110	YEAR	1993	Odom. in	24,983	Odom. out	24,994
-------	-------------------	---------	--------	-------	------	------	------	----------	--------	-----------	--------

Item	Description	Qty	Rate	Amount
LABOR - CO...	6. FOUND THE HOOD RELEASE CABLE TO BE VERY STIFF AND HARD TO OPEN THE HOOD.	0.8	150.00	120.00
PARTS	- REMOVED AND REPLACED HOOD RELEASE CABLE HOOD RELEASE CABLE PUMA STYLE	1	72.55	72.55
LABOR - CO...	7. FOUND THE HVAC DOESN'T WORK ON HIGH. TIME TO DIAG	1	150.00	150.00
PARTS	- FOUND THE FUSE UNDER THE HOOD TO BE CORRODED AND MELTED. REPLACED FUSE AND CLEANED UP FUSE HOLDER, HVAC FAN IS NOW WORKING AS DESIGNED. FUSE	1	0.00	0.00
LABOR - CO...	8. FOUND THE REAR WIPER TO BE INOP. TIME TO DIAG	1.5	150.00	225.00
PARTS	- FOUND NO POWER GOING TO THE REAR DOOR. CHECKED FUSES. FOUND FUSE BLOWN. REPLACED FUSE. RECHECKED FOR POWER AND FOUND POWER AT THE RELAY AND CONNECTOR FOR REAR WIPER MOTOR, BUT MOTOR STILL INOP. SUGGEST REPLACING REAR WIPER MOTOR. - REMOVED AND REPLACED REAR WIPER MOTOR. REAR WIPER IS NOW WORKING PROPERLY REAR WIPER MOTOR GENUINE	1	289.95	289.95

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW ANY WARRANTIES ON THE PRODUCT SOLD HEREIN ARE THOSE MADE BY THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN CASE OF FIRE, THEFT OR OTHER CAUSES BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

x _____

Subtotal
Sales Tax (6.25%)
Total
Payments/Credits
Balance Due

Cityside Garage Ltd.
 330 Hopping Brook Rd.
 Unit 3
 Holliston, MA 01746

508-429-4336

Fax # 508-429-2178



service@citysidegarage.com

Invoice

Invoice #	Bill To	
87148	COPLEY MOTORCARS CORPORATION 37 CHESTNUT STREET NEEDHAM, MA. 02492	
8/30/2022	Customer Phone	781-444-4646

Vin #	SALDH1287PA920210	Plate #	NE31ET	MODEL	D110	YEAR	1993	Odom. in	24,983	Odom. out	24,994
-------	-------------------	---------	--------	-------	------	------	------	----------	--------	-----------	--------

Item	Description	Qty	Rate	Amount
LABOR - CO...	9. FOUND THE BELTS TO BE DRY CRACKING AND WORN. - REMOVED AND REPLACED ALL OF THE BELTS. UPON REMOVAL OF WATER PUMP TENSIONER FOUND BEARING TO BE NOISY AND BOLT IS SEIZED INSIDE OF IT. REPLACED TENSIONER.	1	150.00	150.00
PARTS	BELT KIT	1	65.95	65.95
PARTS	TENSIONER PULLEY, GENUINE ***** ADDED AFTER*****	1	229.95	229.95
LABOR - CO...	10. FOUND THE REVERSE LAMP TO BE INOP. TIME TO DIAG - FOUND FUSE TO BE LOOSE IN THE FUSE PANEL. REMOVED FUSE AND TIGHTENED UP HOLDER. RE INSTALLED FUSE AND REVERSE LAMP IS NOW WORKING AS DESIGNED.	0	150.00	0.00
LABOR - CO...	11. FOUND THE FRONT BUMPER TO BE BENT BACK INTO THE FENDER ON THE PASSENGER SIDE. ONCE BUMPER IS REPLACED, WILL NEED TO GO TO BODY SHOP. - REMOVED AND REPLACED FRONT BUMPER	1	150.00	150.00
PARTS	FRONT BUMPER W/TURN SIGNALS	1	169.95	169.95
PARTS	HARDWARE	1	40.00	40.00
LABOR - CO...	12. FOUND THE FOG LAMPS TO BE WORKING BUT THE LENSES ARE VERY CLOUDY AND VERY LITTLE LIGHT IS PRODUCED. ALSO WIRING IS STARTING TO GET CORRODED. SUGGEST REPLACING. - REMOVED AND REWIRED NEW FOG LAMPS.	1.5	150.00	225.00

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW ANY WARRANTIES ON THE PRODUCT SOLD HERIEEN ARE THOSE MADE B THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NETHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN CASE OF FIRE, THEFT OR OTHER CAUSES BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Subtotal
Sales Tax (6.25%)
Total
Payments/Credits
Balance Due

x _____

Cityside Garage Ltd.
 330 Hopping Brook Rd.
 Unit 3
 Holliston, MA 01746

508-429-4336

Fax # 508-429-2178



service@citysidegarage.com

Invoice

Invoice #	Bill To	
87148	COPLEY MOTORCARS CORPORATION 37 CHESTNUT STREET NEEDHAM, MA. 02492	
8/30/2022	Customer Phone	781-444-4646

Vin #	SALDH1287PA920210	Plate #	NE31ET	MODEL	D110	YEAR	1993	Odom. in	24,983	Odom. out	24,994
-------	-------------------	---------	--------	-------	------	------	------	----------	--------	-----------	--------

Item	Description	Qty	Rate	Amount
PARTS	HELLA 4000	2	323.95	647.90
PARTS	WIRING SUPPLIES	1	50.00	50.00
LABOR - CO...	13. FOUND THE Y-CAT TO MANIFOLD GASKETS TO BE LEAKING	1.8	150.00	270.00
	- LOWERED EXHAUST AND REPLACED BOTH DOWNPIPE GASKETS AND HARDWARE.			
PARTS	DOWNPIPE GASKETS	2	12.95	25.90
PARTS	HARDWARE	1	30.00	30.00
LABOR - CO...	14. FOUND THE Y-CAT TO BE MAKING CONTACT WITH THE CROSSMEMBER.	0.5	150.00	75.00
	- TIME TO HEAT AND REBEND THE Y-CAT			
	- HEATED AND BENT PIPE TO CLEAR CROSS MEMBER.			
LABOR - CO...	15. FOUND THE EXHAUST TO BE LEAKING FROM THE CLAMP BEFORE THE MUFFLER. CLAMP IS ROTTING AWAY	0.2	150.00	30.00
	- REMOVED AND REPLACED EXHAUST CLAMP.			
PARTS	2.5" EXHAUST CLAMP	1	15.95	15.95
LABOR - CO...	16. FOUND THE FRONT AND REAR SHOCK BUSHINGS TO BE WORN AND COMING APART. SUGGEST REPLACING ALL 4 SHOCKS.	4	150.00	600.00
PARTS	SHOCK KIT	1	389.95	389.95

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW ANY WARRANTIES ON THE PRODUCT SOLD HERIEEN ARE THOSE MADE B THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NETHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN CASE OF FIRE, THEFT OR OTHER CAUSES BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Subtotal
Sales Tax (6.25%)
Total
Payments/Credits
Balance Due

x _____

Cityside Garage Ltd.
 330 Hopping Brook Rd.
 Unit 3
 Holliston, MA 01746



508-429-4336

service@citysidegarage.com

Fax # 508-429-2178

Invoice

Invoice #	Bill To	
87148	COPLEY MOTORCARS CORPORATION 37 CHESTNUT STREET NEEDHAM, MA. 02492	
8/30/2022	Customer Phone	781-444-4646

Vin #	SALDH1287PA920210	Plate #	NE31ET	MODEL	D110	YEAR	1993	Odom. in	24,983	Odom. out	24,994
-------	-------------------	---------	--------	-------	------	------	------	----------	--------	-----------	--------

Item	Description	Qty	Rate	Amount
LABOR - CO...	17. FOUND ONE OF THE A/C CONDENSOR FANS TO BE SEIZED. SUGGEST REPLACING BOTH OF THEM.	1	150.00	150.00
PARTS	- REMOVED AND REPLACED BOTH CONDENSOR FANS.			
PARTS	8" ELECTRIC FAN	2	115.99	231.98
PARTS	HARDWARE AND BRAKETS	1	30.00	30.00
Shipping & H...	SHIPPING	1	15.95	15.95
LABOR - CO...	18. AFTER ALL THE WORK WAS DONE, WE FOUND THE TRUCK STILL HAD AN INTERMITTANT RUNABILITY ISSUE, IT WOULD DIE AND NOT RESTART TILL IT COOLED OFF. FOUND THE NEGATIVE BATTERY CONNECTION WAS GETTING VERY HOT AT THE SHUTOFF SWITCH AND FOUND LOTS OF CORROSION ON IT. NECESSARY TO REPLACE THE SWITCH. AFTER WE REPLACED THE SWITCH WE THEN FOUND SOME CORROSION AROUND THE TERMINALS ON THE IGNITION COIL. WE THEN REPLACED THE IGNITION COIL, AFTER THE TEST DRIVE WE HAD NO MORE ISSUES WITH THE TRUCK DYING OR RESTARTING WHEN HOT.	2	150.00	300.00
PARTS	BOSCH IGNITION COIL	1	110.00	110.00
PARTS	BATTERY CUTOFF SWITCH	1	18.95	18.95

PARTS WARRANTY - TO THE EXTENT PERMITTED BY STATE OR LOCAL LAW ANY WARRANTIES ON THE PRODUCT SOLD HERIEEN ARE THOSE MADE B THE MANUFACTURER. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NETHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.
 NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLES OR ARTICLES LEFT IN CASE OF FIRE, THEFT OR OTHER CAUSES BEYOND OUR CONTROL.

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. AN EXPRESS MECHANIC'S LIEN HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO.

Subtotal	\$8,081.97
Sales Tax (6.25%)	\$0.00
Total	\$8,081.97
Payments/Credits	\$0.00
Balance Due	\$8,081.97

x _____